
#### THOSE TRANNYS ROLLING

# VALVE BODY PROBLEMS with Toyota's



by Pete Huscher members.atra.com

U660E, U660F, U760E, and U760F



n this issue of *Keep Those Trannys Rolling*, we're going to look at some of the valve body problems we've encountered on Toyota's U660E, U660F, U760E, and U760F transmissions over the past few years.


These problems include faulty engagements and shifts, TCC-related issues, and problems with the lube circuits.

#### **Engagement Problems**

Delayed or harsh engagement may be caused by a worn primary pressure regulator valve and bore (figure 1).

A delayed or harsh engagement into reverse may be caused by a worn

### A higher level.



## That's what you get with Ford gas engines and transmissions.

A higher build level means you're getting engine and transmission assemblies built to the exacting specifications of Ford Motor Company. So you not only get the quality build you expect in an assembly from Ford, but also one that's built by using parts that keep it specific to year, make and model as well as emissions calibrations.

#### 3-Year/Unlimited-Mile Warranty – No Commercial Exceptions

Ford gasoline engines and transmissions are covered by a three-year/unlimited-mile warranty.\* All warranties are backed by Ford Motor Company. They're also supported by more than 3,000 Ford and Lincoln Dealerships nationwide as well as at their originating place of service.

Plus, unlike some competitors, this warranty is good for fleet vehicles. That means you get the same advantages and coverage for commercial use, no exceptions.

For technical questions, contact the Ford Powertrain Assistance Center at 1-800-392-7946 or visit FordParts.com.
\*See dealer for limited-warranty details. Remanufactured diesel engines are covered by a two-year/unlimited-mile warranty.



A delayed reverse, no reverse, or slipping in reverse may be caused by a worn B2 apply control valve or bore, or a worn B2 control valve or bore.

reverse boost valve and sleeve.

Continuous modulation of the primary pressure regulator valve and reverse boost valve can cause premature valve, bore, and sleeve wear. If you find excessive wear in the primary pressure regulator valve and bore or in the reverse boost valve and sleeve, repair or replace the valve body.


A delayed reverse, no reverse, or slipping in reverse may be caused by a worn B2 apply control valve or bore (figure 2), or a worn B2 control valve or bore (figure 3). Continuous modulation of the B2 apply control valve causes premature wear of the valve body bore.


If you find excessive wear in the B2 apply control valve and bore or the B2 control valve and bore, repair or replace the valve body.

#### **Shift Problems**

Erratic 1-2 and 5-6 shifts or a burnt B1 brake may be caused by wear in the B1 apply boost valve or sleeve (figure 4). If you find excessive wear in the B1 apply boost valve and sleeve, repair or replace the valve body.

A flaring or harsh 4-5 shift may be caused by a worn clutch control valve or bore (figure 5). This wear can cause a loss of SL1 and SL2 pressure, causing an erratic 4-5 shift. If you find excessive clutch control valve or bore wear, repair or replace the valve body.









Show us your hottest ride and you may win a

**\$1000** gift card!





Visit www.TransTec.com/Ride for more information.









Freudenberg-NOK Sealing Technologies









Erratic shifts, solenoid performance codes, and TCC apply and release problems may be caused by a worn solenoid modulator valve or bore (figure 6). Excessive wear in the solenoid modulator valve and bore can cause the valve to side load, resulting in erratic solenoid supply pressure. Repairing the solenoid modulator valve and bore will go a long way to correct erratic shifts.

Harsh or soft shifts into a specific gear may be caused by worn accumulators or accumulator bores (figure 7). Wear in the accumulator bores may allow apply oil to leak, which will cause erratic shifts. Repairing the accumulator bores will correct these problems.






**RMP POWERTRAIN SOLUTIONS** 




- Full Line of Domestic and Import Remanufactured Transmissions, Light to Heavy Duty
- 3 yr/100,000 Mile Nationwide Warranty
- Nationwide Distribution
- Largest Inventory in the Industry


800 257 7418 • sales@rmpparts.com POWERTRAINSOLUTIONS.COM



Erratic shifts, lockup problems, and burnt clutch components may be caused by worn valve body end plugs (figure 8). Worn OEM end plugs may allow line pressure and SLT pressure to leak from around the valve body bores. Installing

O-ringed end plugs during every valve body repair should correct these problems.





## Can You See the Difference?

We didn't think so. The fact is, with remanufactured valve bodies, what you see isn't always what you get. Two valve bodies may look the same, but it's the work that goes into the remanufacturing process that determines how well they perform.

At Valve Body Xpress, we do one thing—remanufacture valve bodies—and we do it better than anyone. Every single one of our premium products is individually tested and calibrated to ensure peak performance. All solenoids are either new or individually tested for integrity and efficiency, and we always include multiple industry updates as well as our own exclusive VB-Xtra updates to guarantee the highest-quality product every time. You can always count on expert product support and customer service when you need it.

This commitment to excellence and confidence in our product is why every valve body we deliver is backed by a *LIFETIME WARRANTY*.

The next time you're in the market for a remanufactured valve body, demand the best. Demand VBX. Call (866) 2GET-VBX or visit us online at www.vbxus.com.





150 MID-ATLANTIC PARKWAY PAULSBORO, NJ 08066

(866) 2GET-VBX www.vbxus.com Lube problems,
bearing or
bushing failures,
and transmission
overheating can be
caused by a worn
secondary pressure
regulator valve or bore.

#### **TCC Problems**

TCC apply and release problems, TCC slip codes, transmission overheating, and torque converter problems may be caused by a worn lockup control boost valve and sleeve (figure 9). This wear may cause the lockup control valve to stroke on or off prematurely, causing erratic TCC operation. Repairing the lockup control boost valve and sleeve may correct erratic TCC operation.

#### **Lube Problems**


Lube problems, bearing or bushing failures, and transmission overheating can be caused by a worn secondary pressure regulator valve or bore (figure 10). Excessive valve or bore wear at the solenoid modulator valve will cause EPC oil and balance oil pressure to leak, reducing lube flow. Repairing the solenoid modulator valve and bore will usually correct this condition.

Well there you have it: a brief look at some of Toyota's U660E, U660F, U760E, and U760F valve body problems and possible fixes. With a better understanding of these valve body problems, you, too, should be able to *keep those trannys rolling*.





Figure 9: Worn Lock-up Control Boost Valve and Sleeve







## FOR QUALIFIED TRANSMISSION SHOPS ONLY



WIT offers remanufactured automatic and manual transmissions. Each transmission is fully dyno-tested and includes a 12 month/unlimited mile warranty on parts and workmanship\*. Extended 2 and 3 year warranties on parts and/or labor available\*. WIT also distributes a complete line of quality new, used and remanufactured automatic and standard transmission parts.

\*Excludes Commercial and Off-Road Vehicles

## 800.940.0197 • www.wittrans.com





In stock for YOU, not your customers!