



ATRA WEBINAR

O1J CVT Introduction

AUTOMATIC TRANSMISSION
REBUILDERS ASSOCIATION

Sponsored By:



Presented by:
Steve Garrett
ATRA



your source for engineered solutions





Today's Presentation Sponsored By:



**SEAL AFTERMARKET
P R O D U C T S**TM

your source for engineered solutions

Phone 954-364-2400 • Toll Free 800-582-2760 • Fax 954-364-2401
www.sealaftermarketproducts.com



your source for engineered solutions





Lwiggins@ATRA.com

- * **Connections**
- * **Handout**
- * **Questions**
- * **Survey**

AUTOMATIC TRANSMISSION
REBUILDERS ASSOCIATION



Thanks


- * A special thanks to Mike Souza and to Audi for help with the information for this presentation

AUTOMATIC TRANSMISSION
REBUILDERS ASSOCIATION



“Audi Multitronic 01J”

Introduction





Introduction

Variable Automatic Gearbox designed by Audi.

Commonly known as Continuously Variable Transmission "CVT".

Designated: Multitronic 01J

Vehicle application:

- 2004-09 A4 Cabriolet 1.8L / 2.0L L4 / 3.0L V6
- 2002-04 A6 3.0L V6
- 2005-09 3.2L V6

Features:

- No fluid coupling (torque converter) between engine and gearbox.
- Single flywheel damper unit (V6 engine).
- Dual-Mass flywheel damper (4 cylinder engine).
- One Forward multi-disc clutch (slipped @ standstill or hill hold).
- One Reverse multi-disc clutch (both act as starting clutches).
- Reverse rotation is created through a planetary gear train.
- Engine torque is transmitted to the final drive via a "variator" by an auxiliary reduction gear step.
- Steel chain instead of a belt driven.
- Electro-hydraulic control unit (valve body) and combined Electronic Control Module (located in the gearbox housing).
- Tiptronic function; provides 6 forward "speeds" for manual gear selection, performed by the driver through either the console shifter or steering wheel paddle buttons.
- Stepless ratio changes controlled by a "Variator" (two variable tapered pulleys and connecting chain) for optimal fuel utilization and driver comfort.
- Primary variable tapered drive pulley driven by engine torque.
- Secondary variable tapered driven pulley driven by steel chain.



Specifications

Designation: multitronic®01J

Factory designation: VL 30

Code: DZN

Max. transferable torque: max. 310 Nm

Range of ratios of the variator: 2.40 - 0.40

Spread: 6

Ratio of auxiliary reduction gear step: $51/46 = 1.109 : 1$

Final drive ratio: $43/9 = 4.778 : 1$

Operating pressure of oil pump: max. approx. 60 bar

Delivery rate of oil pump: 10 lpm @ 1000 rpm

ATF for multitronic®:G 052 180 A2

Axle oil for multitronic®:G 052 190 A2

Gear oil quantities:

ATF new filling (incl. ATF cooler and ATF filter) approx. 7.5 litres

ATF change approx. 4.5 litres

Axle oil approx. 1.3 litres

Gross weight (without flywheel): approx. 88 kg

Overall length: approx. 610 mm



Modes of Operation

- **Tiptronic (6 speeds, manual control)**
- **Multitronic**

AUTOMATIC TRANSMISSION
REBUILDERS ASSOCIATION



Shift Modes.

AUTOMATIC: All 6 ratios are controlled by a preprogrammed strategy of the vehicles onboard computer. The conditions that determine ratio change are controlled by driver input, such as accelerator pedal position in conjunction with traction resistance. The ratios are completed smoothly without any interruption.

Tiptronic Mode:

There are 6 defined shifting ratios for manual gear selection. The driver can choose handling dynamics to suit personal preference. This feature can be used on downhill grades, such as an engine braking effect controlled by selective down shifting. This feature will only allow a top speed in 5th gear. The 6th gear ratio is commanded for a more efficient fuel economy or overdrive. The “tiptronic mode” can be operated by the console shifter or shift paddles/buttons (optional) located on the steering wheel

REBUILDERS ASSOCIATION



Shift Modes



Triptronic






Flywheel Damper Assembly

No Torque Converter





Drive -Train Layout





“Variator Function”


The variator allows for a smooth continuous reduction of ratio from standstill to maximum speed. The correct ratio is commanded for optimum speed range, engine performance and fuel economy. The variator consists of two pairs of tapered disc pulleys, one Primary pulley set (1) one Secondary pulley set (2) and a special chain that runs in the V-shaped gap between the two tapered pulley sets. The chain is the primary power element of the transmission. Primary pulley set (1) is driven by the engine via an auxiliary reduction gear step. Torque is transmitted through the chain to the secondary pulley set (2) and to the final drive. One of the tapered pulleys in each set is hydraulically controlled to variably adjust the chain track diameter and change the transmission ratio. Both pulleys sets must be controlled simultaneously so that the chain is always kept taut. The disc and chain contact pressure though all ratios must be in proportion to transmission torque in order to prevent slipping.



Variator Function


Audi multitronic

10/99






Forward / Reverse Clutch & Planet Assembly






Forward / Reverse Clutch Assembly




Front Cover & Input Shaft

Vent




Forward / Reverse Clutch & Planet Assembly




Front Seal

Snap Ring




Pressed out



Forward Clutch & Planet Assembly


Reverse Clutch Assembly



Splined



Communication







Multitronic Control Unit


No Movement / Delays

Metal Contamination






Solenoid ID & Function




- N88: Cooling Clutch & Safety Valve (Solenoid)**
- N215: Clutch Control Valve (Solenoid)**
- N216: Reduction Valve (Solenoid)**

Pressure control valve (proportional valve)



Sump

Diagram of pressure control valve






Speed Sensor (Input) G182

**Multitronic Control Unit's
Dynamic Control Program
(DRP)**

**Monitors Input Speed Sensor # 1
Signal From Pulley Set # 1 In
Comparison To Output Speed &
Engine RPM To Control The
Amperage To The
N216 Solenoid For Pulley
Contact Pressure Control**





Gearbox input speed sender G182 and gearbox output speed senders G195 and G196

Speed Sensor (Output) G195 & G196

Must use a scan Tool to diagnose Sensors

Do not Pry on Sensors
Sometimes they Are mistaken For seals

G 182= ISS
G 195/196= OSS

Gearbox output speed senders G195 and G196


Sender wheel for G195 and G196

32 Magnets

Gearbox input speed sender G182

Sender wheel for G182

40 Magnets






228_078



2 Speed Sensors (Output)


By having
Them out
Of phase
The TCM
Can
Determine
Direction






Sensors (Hydraulic Pressure) G193 & G194

Clutch Pressure



G193 Monitors FWD and REV
Clutch PSI


Contact Pressure



G194 Monitors contact PSI
Regulated by the torque
sensor




Switches (Multifunction) F125



Monitors Shifter Position for:

- Starter
- Reverse Lights
- P/N Shift Lock
- Clutch control Fwd/Rev/Neutral
- Locks ratio in REV



F125

(4 Hall Sensors (A B C D))




Switches (Multifunction) F125

Gearshift combinations


Selector lever position	Hall sensors			
	A	B	C	D
P	0	1	0	1
between P-R	0	1	0	0
R	0	1	1	0
between R-N	0	0	1	0
N	0	0	1	1
between N-D	0	0	1	0
D	1	0	1	0
Fault	0	0	0	0
Fault	0	0	0	1
Fault	0	1	1	1
Fault	1	0	0	0
Fault	1	0	0	1
Fault	1	0	1	1
Fault	1	1	0	0
Fault	1	1	0	1
Fault	1	1	1	0
Fault	1	1	1	1

Signal for shift indicator on multitronic® - P, R, N, D






Switches (Multifunction) F125





Switches (Brake) F47




**Creep Control
Shifter Lock
Dynamic Control Program**




Switches (No Kickdown Switch)

If the accelerator pedal module is replaced, the “kickdown” shift point must be readapted using capable scan tool software


Accelerator pedal module G79/G185



Engine control unit J220



CAN




Gearbox control unit J217


**Spring Loaded Pressure Element
(Kickdown Switch Feel)
Monitors Pedal Position**



Clutch Pressure Control



**N215 solenoid
Command
Based on
Clutch pressure
Load Calculation
And ratio**





“Safety Shut Off” Activation


Position After “Safety Shut Off” Switched

Clutch Pressure
Becomes Higher
Than Control Pressure

“Overload Protection”
Trans Temperature Too High
Engine Will Be Forced
To Idle Until A Short Clutch
Cooling System Time Period

In the event that actual clutch pressure becomes higher than the control pressure (due to a malfunction), the safety shut off function will exhaust clutch pressure. No matter where the manual valve is positioned

Feed Blocked
Exhausted




Solenoid
Pressure

- Vented into oil sump/depressurised
- Clutch pressure
- Supply pressure
- Pilot control pressure
- Control pressure
- In the oil sump



Creep Control





**“Hill Hold” & “Micro Slip” Feature
Increased Clutch Pressure
Decrease In slip**

When the vehicle is at a standstill the creep control function sets the clutch to a calibrated slip rate (torque). With the engine idling in drive (brakes released) the clutch slip functions the same as an automatic transmission torque converter.



Clutch Cooling System




The cooling oil is only directed to the clutch in use.




Contact Pressure Control (N216)

Underdrive




Over drive






Auxiliary Reduction Gear Set



Torque Sensor



The torque sensor is a hydromechanical sensor located on pulley set 1. The sensor is compiled of 2 shells and 7 steel balls. One ramp shell is connected to the output gear the other splined onto the torque sensor piston attached to pulley set 1. This ramp shell and ball assembly statically and dynamically controls the contact pressure through torque sensor spaces. The 2 shells rotate towards each other. Forces from ramp shell 1 converts engine torque to ramp shell 2, pushing the torque sensor piston. This movement opens and closes the outlets to sensor space 1.




Splash Oil Cover

The “splash oil cover” is located on pulley set 2 to counteract the pressure build up in the pressure cylinder. At higher engine speeds

AUTOM
REBU



Balance Oil






1st by Audi

Chain




Different lengths of link plate


228_028



Cradle type pressure pieces




Top view



Shackle

Side view



Cradle type pressure pieces

Cradle type joint


228_027

AUTOMATIC TRANSMISSION REBUILDERS ASSOCIATION



Suction Jet Pump (Entrainment Pump)

The suction jet pump (entrainment pump) is mounted directly on the valve body driven by the input shaft. This is a crescent type pump that produces high pressure and volume with a small amount of oil. The suction entrainment pump is designed to supply the oil volume required for the clutch cooling at low pressure






Hydraulic Control Unit (Valve Body)

Valve body functions:

- *Forward/Reverse clutch control
- *Clutch pressure control (regulated)
- *Clutch cooling
- *Contact pressure control
- *Gearbox control
- *Splash oil







Hydraulic Control Unit (Valve Body)

- * **DBV1: Pressure Limiting valve** (limits the pump pressure to max. 82 bar “blow off”)
- * **DBV2: Pressure Limiting valve 2**
- * **Minimum Pressure valve** (prevents air from being drawn into the oil pump during start up/when pump pressure is high valve opens and allows oil to flow from the oil return pipe to the suction side of the oil pump)
- * **VSTV: Pilot Pressure valve** (supplies pressure control valves constant pressure of 5 bar)
- * **VSPV: Pressure control valve** (system pressure (control and contact pressure))
- * **KKV: Clutch cooling valve**
- * **KSV: Clutch control valve**

Hydraulic control unit
(gearbox control unit removed)





Sectional view of valve plate





Hydraulic Control Unit (Valve Body)







PRND Display Normal “Non Critical” No Noticeable Drive Ability Issues

Fault Indicator



PRND Display Inverted Still “Non Critical” Should Be Corrected As Soon As Possible



PRND Display “FLASHING” Critical Should Be Corrected Immediately Will Stop Operating



**No
Movement**



May Not Make Noise

**Variator Assembly With
Chain \$800.00**



**Piston &
Drum Wear**



Replace TCM



Technical Service Bulletin

MIL on, and/or Multitronic Transmission in Emergency Running Mode (DTC P0706 or P1793 in TCM)

37 07 10 May 31, 2007 2012154/8. Supersedes Technical Service Bulletin Group 37 number 07-09 dated May 30, 2007 to add a transmission code to the header data within ElsaWeb.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4	2002 – 2007	All	Automatic CVT (D1J)
A4 Cabriolet	2003 – 2007	All	
A6	2002 – 2004, 2006 – 2007	All	

Condition

MIL on and/or vehicle in emergency running mode with gear indicator illumination inverted. DTC 17090-P0706 (Transm. Range Sensor Circ. Range/Performance) or DTC 18201-P1793 (Output Speed Sensor 2 Circ. No Signal).

DTC 17090 / P0706 Range Sensor 18201 / P1793 OSS

Technical Background

Not applicable.



Production Solution

Not applicable.

Inverted

Service

It is *not* necessary to receive an authorization number from the Technical Assistance Center for the repair described in this bulletin.

Attach VAS scan tool printouts to the repair order. Warranty requested documents received without VAS scan tool printouts will be denied payment.

If either DTC 17090-P0706 or 18201-P1793 is stored in the fault memory, **replace Transmission Control Module.** Refer to *Group 38, Transmission Control Module (TCM) J217 Removing and Installing.*

Warranty

No Drive / Delay In Drive Or Reverse



Technical Service Bulletin

No drive or delayed drive in "D" or "R" (DTC P1743/18151 may be stored in TCM)

38 07 01 Jan 9, 2007, 2013280/1

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6	2006-2007	All	With Automatic CVT (01J)
A4	2006	All	
A4 Cabriolet	2005-2006	All	

Condition

DTC 18151 / P1743

No drive, or delayed drive when either D or R is selected. DTC P1743/18151 may be logged in TCM fault memory.

The vehicle does not start moving without accelerating. When accelerating, an increased engine speed is necessary to move the vehicle. In some cases there is no drive.

Technical Background

Increase Engine Speed For Movement

Some damaged seals installed in production.

The damaged seals may leak after a short operating period (less than 13,000 miles), causing a loss of transmission oil pressure.

This condition will not result in unintentional vehicle movement.

Affected vehicles: Vehicles with Multitronic transmissions produced between May 2005 and May 2006.

Production Solution

Improved production.

Service

It is *not* necessary to receive an authorization number from the Technical Assistance Center for the repair described in this bulletin.


Attach VAS scan tool printouts to the repair order. Warranty requested documents received without VAS scan tool printouts will be denied payment.

If fault P1743/18151 (clutch slip monitoring signal too large) is stored in the transmission fault memory, read MVB 44/1 and 45/1. If MVB 44/1 is 1000 mA and MVB 45/1 is above 12 bar, there is a problem with the axial seals. If MVB 45/1 is below 12 bar, this indicates a hydraulic problem. (See below for further analysis.)

No Drive / Delay In Drive

AUTOMATIC TRANSMISSION
REBUILDERS ASSOCIATION

4
Seals




Valve Body Removed



A38-0094

Delay In Reverse




Front Cover
Removed

A38-0117



Reverse Clutch Tube

Forward Clutch Tube



Reverse clutch

Reverse Clutch
Tube

Ring gear

Forward Clutch Tube

Oil pressure for clutch
Torque flow

Pulley Set # 1

Chain Removal

**Audi Has A TSB To
Remove 2 Links
(Drive Pins Out)**

**Without Removing The Differential
With Special Press**



Replace TCM



Technical Service Bulletin

MIL on, and/or Multitronic Transmission in Emergency Running Mode (DTC P0706 or P1793 in TCM)
37 07 10 May 31, 2007 2012154/8. Supersedes Technical Service Bulletin Group 37 number 07-09 dated May 30, 2007 to add a transmission code to the header data within ElsaWeb.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4	2002 – 2007	All	Automatic CVT (01J)
A4 Cabriolet	2003 – 2007	All	
A6	2002 – 2004, 2006 – 2007	All	

Condition

MIL on and/or vehicle in emergency running mode with gear indicator illumination inverted. DTC 17090-P0706 (Transm. Range Sensor Circ. Range/Performance) or DTC 18201-P1793 (Output Speed Sensor 2 Circ. No Signal).

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

It is *not* necessary to receive an authorization number from the Technical Assistance Center for the repair described in this bulletin.

Attach VAS scan tool printouts to the repair order. Warranty requested documents received without VAS scan tool printouts will be denied payment.

Inverted

If either DTC 17090-P0706 or 18201-P1793 is stored in the fault memory, replace Transmission Control Module. Refer to Group 38, *Transmission Control Module (TCM) J217 Removing and Installing*.

Warranty

© 2007 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reported to other sites, without the prior expressed written permission of the publisher.

**DTC 17090 / P0706
Range Sensor
18201 / P1793 OSS**





**No Drive / Delay
In Drive Or
Reverse**

**Increase Engine
Speed
For Movement**



67

Technical Service Bulletin

No drive or delayed drive in "D" or "R" (DTC P1743/18151 may be stored in TCM)

38 07 01 Jan 9, 2007, 2013280/1

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6	2006-2007	All	With Automatic CVT (01J)
A4	2006	All	
A4 Cabriolet	2006-2006	All	

Condition

No drive, or delayed drive when either D or R is selected. DTC P1743/18151 may be logged in TCM fault memory.

The vehicle does not start moving without accelerating. When accelerating, an increased engine speed is necessary to move the vehicle. In some cases there is no drive.

Technical Background

Some damaged seals installed in production.

The damaged seals may leak after a short operating period (less than 13,000 miles), causing a loss of transmission oil pressure.

This condition will not result in unintentional vehicle movement.

Affected vehicles: Vehicles with Multitronic transmissions produced between May 2005 and May 2006.

Production Solution

Improved production.

Service

It is *not* necessary to receive an authorization number from the Technical Assistance Center for the repair described in this bulletin.

Attach VAS scan tool printouts to the repair order. Warranty requested documents received without VAS scan tool printouts will be denied payment.

If fault P1743/18151 (clutch slip monitoring signal too large) is stored in the transmission fault memory, read MVB 44/1 and 45/1. If MVB 44/1 is 1000 mA and MVB 45/1 is above 12 bar, there is a problem with the axial seals. If MVB 45/1 is below 12 bar, this indicates a hydraulic problem. (See below for further analysis.)

Page 1 of 4

© 2006 Audi of America, Inc.
All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

**DTC 18151 /
P1743**




your source for engineered solutions



No Drive / Delay In Drive

AUTOMATIC TRANSMISSION
REBUILDERS ASSOCIATION

4
Seals




Valve Body Removed

A

A38-0094

Delay In Reverse



Front Cover
Removed

A38-0117



Today's Presentation Sponsored By:



**SEAL AFTERMARKET
PRODUCTS™**
your source for engineered solutions

Phone 954-364-2400 • Toll Free 800-582-2760 • Fax 954-364-2401
www.sealaftermarketproducts.com



THANK YOU



your source for engineered solutions





Thanks For Attending

- * **Questions**
 - * **Survey**
 - * **Thanks For Attending, See you during our Next ATRA webinar**
- Thanks to our supplier for the support**